



Title: Migrating to MCAPI 3.4.1 or Later on Windows 98/Me
Products(s): MCAPI
Keywords: MCAPI, migrate, Windows 98, Windows Me
ID#: TN1052
Date: November 20, 2003

Summary

When upgrading the Motion Control API (MCAPI) you need to successfully uninstall the previous version first. There is a bug in versions of the MCAPI older than 3.4.0 running on Windows 98 or Windows Me that can lead to a blue-screen if you attempt to uninstall a motion controller.

More Information

To avoid the bug and allow the uninstall to complete please use the following sequence:

- Shut the PC down and remove all motion controllers (this will prevent the low-level device driver from loading).
- Boot the PC and use the add/remove programs applet in the Windows Control Panel to remove the Motion Control API
- Restart the PC to complete the un-install
- Follow the installation instructions included with the new version of the MCAPI for your operating system and controller model

The information in this TechNOTE is also included in the README.TXT file that accompanies the latest version of the MCAPI.